

Technical bulletin: PLT Dimming below 10%

TUNABLE PANEL LIGHTS



A few customers have noted dimming issues for the tuneable panels when multiple units are grouped on a single remote. Notably, uneven dimming or drop-out (turn-off). This is not a flaw but rather a function of design.

Please note, the panels are not intended to be dimmed below 10%. Uneven dimming will result and some may turn completely off before others.

Synchronized “Dim to off” LED drivers require more sophisticated electronic circuits which will significantly add to the cost of the product.

